

# EQ SWT Moving-iron current meter



EQ..n SWT-3 / EQ..n SWT-6 Voltmeter with changeover switch  
Precise voltmeter for measuring voltages between phases or phase-neutral. With selector switch for easy switching between the measuring lines. The EQ..n SWT-3 also has a switch-off position.  
Features:  
• Frequency range: 25 to 100 Hz  
• RMS measurement even with harmonics  
• Overload-resistant: 1.2 × UN continuous, 2 × UN (5 s)  
• Max. Consumption: 3.5 VA  
• Vibration and shock resistant  
•

Beispielbild

## Variants (130)

| Article no.  | Description                                  |
|--------------|----------------------------------------------|
| 70097-1643-9 | EQ72n SWT-6 0-300V AC Voltmeter              |
| 70097-1644-9 | EQ72n SWT-3 0-500V AC Voltmeter              |
| 70097-1645-9 | EQ72n SWT-6 0-500V AC Voltmeter              |
| 70097-1646-9 | EQ72n SWT-6 0-600V AC Voltmeter              |
| 70097-1716-9 | EQ96n SWT-3 0-400V AC Voltmeter              |
| 70097-1717-9 | EQ96n SWT-6 0-400V AC Voltmeter              |
| 70097-1718-9 | EQ96n SWT-3 0-500V AC Voltmeter              |
| 70097-1719-9 | EQ96n SWT-6 0-500V AC Voltmeter              |
| 70097-1720-9 | EQ96n SWT-3 0-600V AC Voltmeter              |
| 70097-1721-9 | EQ96n SWT-6 0-600V AC Voltmeter              |
| 70097-3373-9 | EQ72n SWT-3 0-600V AC Voltmeter              |
| 70097-3438-9 | EQ72n SWT-6 0-400V AC Voltmeter              |
| 70097-3515-9 | EQ96n SWT-3 0-250V AC Voltmeter              |
| 70097-3647-9 | EQ72n SWT-3 0-400V AC Voltmeter              |
| 70097-3937-9 | EQ72n SWT-3 0-300V AC Voltmeter              |
| 70097-4997-9 | EQ72n SWT-3 500/600/100V AC (x1,2) Voltmeter |

| Article no.  | Description                                        |
|--------------|----------------------------------------------------|
| 70097-4998-9 | EQ72n SWT-3 600/720/100V AC (x1,2) Voltmeter       |
| 70097-4999-9 | EQ72n SWT-3 1000/1200/100V AC (x1,2) Voltmeter     |
| 70097-5000-9 | EQ72n SWT-3 3000/3600/100V AC (x1,2) Voltmeter     |
| 70097-5001-9 | EQ72n SWT-3 5000/6000/100V AC (x1,2) Voltmeter     |
| 70097-5002-9 | EQ72n SWT-3 6000/7200/100V AC (x1,2) Voltmeter     |
| 70097-5003-9 | EQ72n SWT-3 10000/12000/100V AC (x1,2) Voltmeter   |
| 70097-5004-9 | EQ72n SWT-3 15000/18000/100V AC (x1,2) Voltmeter   |
| 70097-5005-9 | EQ72n SWT-3 20000/24000/100V AC (x1,2) Voltmeter   |
| 70097-5006-9 | EQ72n SWT-3 25000/30000/100V AC (x1,2) Voltmeter   |
| 70097-5007-9 | EQ72n SWT-3 30000/36000/100V AC (x1,2) Voltmeter   |
| 70097-5008-9 | EQ72n SWT-3 33000/40000/100V AC (x1,2) Voltmeter   |
| 70097-5009-9 | EQ72n SWT-3 60000/72000/100V AC (x1,2) Voltmeter   |
| 70097-5010-9 | EQ72n SWT-3 100000/120000/100V AC (x1,2) Voltmeter |
| 70097-5012-9 | EQ72n SWT-3 500/600/110V AC (x1,2) Voltmeter       |
| 70097-5013-9 | EQ72n SWT-3 600/720/110V AC (x1,2) Voltmeter       |
| 70097-5014-9 | EQ72n SWT-3 1000/1200/110V AC (x1,2) Voltmeter     |
| 70097-5015-9 | EQ72n SWT-3 3000/3600/110V AC (x1,2) Voltmeter     |
| 70097-5016-9 | EQ72n SWT-3 5000/6000/110V AC (x1,2) Voltmeter     |
| 70097-5017-9 | EQ72n SWT-3 6000/7200/110V AC (x1,2) Voltmeter     |
| 70097-5018-9 | EQ72n SWT-3 10000/12000/110V AC (x1,2) Voltmeter   |
| 70097-5019-9 | EQ72n SWT-3 15000/18000/110V AC (x1,2) Voltmeter   |
| 70097-5020-9 | EQ72n SWT-3 20000/24000/110V AC (x1,2) Voltmeter   |
| 70097-5021-9 | EQ72n SWT-3 25000/30000/110V AC (x1,2) Voltmeter   |
| 70097-5022-9 | EQ72n SWT-3 30000/36000/110V AC (x1,2) Voltmeter   |
| 70097-5023-9 | EQ72n SWT-3 33000/40000/110V AC (x1,2) Voltmeter   |
| 70097-5024-9 | EQ72n SWT-3 60000/72000/110V AC (x1,2) Voltmeter   |
| 70097-5025-9 | EQ72n SWT-3 100000/120000/110V AC (x1,2) Voltmeter |
| 70097-5026-9 | EQ72n SWT-6 500/600/100V AC (x1,2) Voltmeter       |
| 70097-5027-9 | EQ72n SWT-6 600/720/100V AC (x1,2) Voltmeter       |
| 70097-5028-9 | EQ72n SWT-6 1000/1200/100V AC (x1,2) Voltmeter     |
| 70097-5029-9 | EQ72n SWT-6 3000/3600/100V AC (x1,2) Voltmeter     |
| 70097-5030-9 | EQ72n SWT-6 5000/6000/100V AC (x1,2) Voltmeter     |
| 70097-5031-9 | EQ72n SWT-6 6000/7200/100V AC (x1,2) Voltmeter     |
| 70097-5032-9 | EQ72n SWT-6 10000/12000/100V AC (x1,2) Voltmeter   |
| 70097-5033-9 | EQ72n SWT-6 15000/18000/100V AC (x1,2) Voltmeter   |
| 70097-5034-9 | EQ72n SWT-6 20000/24000/100V AC (x1,2) Voltmeter   |

| Article no.  | Description                                        |
|--------------|----------------------------------------------------|
| 70097-5035-9 | EQ72n SWT-6 25000/30000/100V AC (x1,2) Voltmeter   |
| 70097-5036-9 | EQ72n SWT-6 30000/36000/100V AC (x1,2) Voltmeter   |
| 70097-5037-9 | EQ72n SWT-6 33000/40000/100V AC (x1,2) Voltmeter   |
| 70097-5038-9 | EQ72n SWT-6 60000/72000/100V AC (x1,2) Voltmeter   |
| 70097-5039-9 | EQ72n SWT-6 100000/120000/100V AC (x1,2) Voltmeter |
| 70097-5041-9 | EQ72n SWT-6 500/600/110V AC (x1,2) Voltmeter       |
| 70097-5042-9 | EQ72n SWT-6 600/720/110V AC (x1,2) Voltmeter       |
| 70097-5043-9 | EQ72n SWT-6 1000/1200/110V AC (x1,2) Voltmeter     |
| 70097-5044-9 | EQ72n SWT-6 3000/3600/110V AC (x1,2) Voltmeter     |
| 70097-5045-9 | EQ72n SWT-6 5000/6000/110V AC (x1,2) Voltmeter     |
| 70097-5046-9 | EQ72n SWT-6 6000/7200/110V AC (x1,2) Voltmeter     |
| 70097-5047-9 | EQ72n SWT-6 10000/12000/110V AC (x1,2) Voltmeter   |
| 70097-5048-9 | EQ72n SWT-6 15000/18000/110V AC (x1,2) Voltmeter   |
| 70097-5049-9 | EQ72n SWT-6 20000/24000/110V AC (x1,2) Voltmeter   |
| 70097-5050-9 | EQ72n SWT-6 25000/30000/110V AC (x1,2) Voltmeter   |
| 70097-5051-9 | EQ72n SWT-6 30000/36000/110V AC (x1,2) Voltmeter   |
| 70097-5052-9 | EQ72n SWT-6 33000/40000/110V AC (x1,2) Voltmeter   |
| 70097-5053-9 | EQ72n SWT-6 60000/72000/110V AC (x1,2) Voltmeter   |
| 70097-5054-9 | EQ72n SWT-6 100000/120000/110V AC (x1,2) Voltmeter |
| 70097-5055-9 | EQ96n SWT-3 0-300V AC Voltmeter                    |
| 70097-5056-9 | EQ96n SWT-3 500/600/100V AC (x1,2) Voltmeter       |
| 70097-5057-9 | EQ96n SWT-3 600/720/100V AC (x1,2) Voltmeter       |
| 70097-5058-9 | EQ96n SWT-3 1000/1200/100V AC (x1,2) Voltmeter     |
| 70097-5059-9 | EQ96n SWT-3 3000/3600/100V AC (x1,2) Voltmeter     |
| 70097-5060-9 | EQ96n SWT-3 5000/6000/100V AC (x1,2) Voltmeter     |
| 70097-5061-9 | EQ96n SWT-3 6000/7200/100V AC (x1,2) Voltmeter     |
| 70097-5062-9 | EQ96n SWT-3 10000/12000/100V AC (x1,2) Voltmeter   |
| 70097-5063-9 | EQ96n SWT-3 15000/18000/100V AC (x1,2) Voltmeter   |
| 70097-5064-9 | EQ96n SWT-3 20000/24000/100V AC (x1,2) Voltmeter   |
| 70097-5065-9 | EQ96n SWT-3 25000/30000/100V AC (x1,2) Voltmeter   |
| 70097-5066-9 | EQ96n SWT-3 30000/36000/100V AC (x1,2) Voltmeter   |
| 70097-5067-9 | EQ96n SWT-3 33000/40000/100V AC (x1,2) Voltmeter   |
| 70097-5068-9 | EQ96n SWT-3 60000/72000/100V AC (x1,2) Voltmeter   |
| 70097-5069-9 | EQ96n SWT-3 100000/120000/100V AC (x1,2) Voltmeter |
| 70097-5070-9 | EQ96n SWT-3 500/600/110V AC (x1,2) Voltmeter       |
| 70097-5071-9 | EQ96n SWT-3 600/720/110V AC (x1,2) Voltmeter       |

| Article no.  | Description                                        |
|--------------|----------------------------------------------------|
| 70097-5072-9 | EQ96n SWT-3 1000/1200/110V AC (x1,2) Voltmeter     |
| 70097-5073-9 | EQ96n SWT-3 3000/3600/110V AC (x1,2) Voltmeter     |
| 70097-5074-9 | EQ96n SWT-3 5000/6000/110V AC (x1,2) Voltmeter     |
| 70097-5075-9 | EQ96n SWT-3 6000/7200/110V AC (x1,2) Voltmeter     |
| 70097-5076-9 | EQ96n SWT-3 10000/12000/110V AC (x1,2) Voltmeter   |
| 70097-5077-9 | EQ96n SWT-3 15000/18000/110V AC (x1,2) Voltmeter   |
| 70097-5078-9 | EQ96n SWT-3 20000/24000/110V AC (x1,2) Voltmeter   |
| 70097-5079-9 | EQ96n SWT-3 25000/30000/110V AC (x1,2) Voltmeter   |
| 70097-5080-9 | EQ96n SWT-3 30000/36000/110V AC (x1,2) Voltmeter   |
| 70097-5081-9 | EQ96n SWT-3 33000/40000/110V AC (x1,2) Voltmeter   |
| 70097-5082-9 | EQ96n SWT-3 60000/72000/110V AC (x1,2) Voltmeter   |
| 70097-5083-9 | EQ96n SWT-3 100000/120000/110V AC (x1,2) Voltmeter |
| 70097-5084-9 | EQ96n SWT-6 0-300V AC Voltmeter                    |
| 70097-5085-9 | EQ96n SWT-6 500/600/100V AC (x1,2) Voltmeter       |
| 70097-5086-9 | EQ96n SWT-6 600/720/100V AC (x1,2) Voltmeter       |
| 70097-5087-9 | EQ96n SWT-6 1000/1200/100V AC (x1,2) Voltmeter     |
| 70097-5088-9 | EQ96n SWT-6 3000/3600/100V AC (x1,2) Voltmeter     |
| 70097-5089-9 | EQ96n SWT-6 5000/6000/100V AC (x1,2) Voltmeter     |
| 70097-5090-9 | EQ96n SWT-6 6000/7200/100V AC (x1,2) Voltmeter     |
| 70097-5091-9 | EQ96n SWT-6 15000/18000/100V AC (x1,2) Voltmeter   |
| 70097-5092-9 | EQ96n SWT-6 20000/24000/100V AC (x1,2) Voltmeter   |
| 70097-5093-9 | EQ96n SWT-6 25000/30000/100V AC (x1,2) Voltmeter   |
| 70097-5094-9 | EQ96n SWT-6 30000/36000/100V AC (x1,2) Voltmeter   |
| 70097-5095-9 | EQ96n SWT-6 33000/40000/100V AC (x1,2) Voltmeter   |
| 70097-5096-9 | EQ96n SWT-6 60000/72000/100V AC (x1,2) Voltmeter   |
| 70097-5097-9 | EQ96n SWT-6 100000/120000/100V AC (x1,2) Voltmeter |
| 70097-5098-9 | EQ96n SWT-6 500/600/110V AC (x1,2) Voltmeter       |
| 70097-5099-9 | EQ96n SWT-6 600/720/110V AC (x1,2) Voltmeter       |
| 70097-5100-9 | EQ96n SWT-6 1000/1200/110V AC (x1,2) Voltmeter     |
| 70097-5101-9 | EQ96n SWT-6 3000/3600/110V AC (x1,2) Voltmeter     |
| 70097-5102-9 | EQ96n SWT-6 5000/6000/110V AC (x1,2) Voltmeter     |
| 70097-5103-9 | EQ96n SWT-6 6000/7200/110V AC (x1,2) Voltmeter     |
| 70097-5104-9 | EQ96n SWT-6 10000/12000/110V AC (x1,2) Voltmeter   |
| 70097-5105-9 | EQ96n SWT-6 15000/18000/110V AC (x1,2) Voltmeter   |
| 70097-5106-9 | EQ96n SWT-6 20000/24000/110V AC (x1,2) Voltmeter   |
| 70097-5107-9 | EQ96n SWT-6 25000/30000/110V AC (x1,2) Voltmeter   |

| Article no.  | Description                                        |
|--------------|----------------------------------------------------|
| 70097-5108-9 | EQ96n SWT-6 30000/36000/110V AC (x1,2) Voltmeter   |
| 70097-5109-9 | EQ96n SWT-6 33000/40000/110V AC (x1,2) Voltmeter   |
| 70097-5110-9 | EQ96n SWT-6 60000/72000/110V AC (x1,2) Voltmeter   |
| 70097-5111-9 | EQ96n SWT-6 100000/120000/110V AC (x1,2) Voltmeter |
| 70097-5274-9 | EQ96n SWT-6 0-250V AC Voltmeter                    |
| 70097-5275-9 | EQ96n SWT-6 10000/12000/100V AC (x1,2) Voltmeter   |